

KASKADE

STONE

Stone Cast Bath Installation Manual




IMPORTANT INFORMATION

Ensure the hot water service is set to no higher than 55°C

Inspect bath prior to installation. Claims for damage
or defects will not be accepted after installation.


ALL WORK TO BE CARRIED OUT BY A LICENSED PLUMBER.

Suitable for all bath shapes




Inspect bath prior to installation. Claims for damage or defects will not be accepted after installation.

1



2



3

